



## General renovation of the runway system 11/29 at Schwechat airport

### Data and facts

Company	TEERAG-ASDAG in working group
Type	Airport construction, Asphalt and concrete production
Runtime	04.2015 - 06.2016
Principal	Flughafen Wien AG

[Project report online](#)

[www.porr-group.com](http://www.porr-group.com)




# Restoration under strictest safety regulations.

In the course of general renovation of the runway system 11/29 the following measures were carried out:

- Fillet broadening in the areas of Exit 1-6 and Exit 8-11
- Fillet broadening in the areas A4, A6, A7, A8, A9, A11 and A12
- Renovation of taxiway in the area A4
- Relocation of the taxiway centrelines lighting in the areas A4 and EX4
- Updating above ground edge lighting in the area of taxiway A4, A6, A7, A8, A9, A11 and A12 from the runway coming to the holding point
- Updating the taxiway lighting in the area of taxiway broadening at the taxiways A4, A6, A9 and A11
- Reallocation of boundary markers in the taxiway and exit areas north of the taxi-holding position

## Impressions



## Image notes

1

General renovation of the runway system 11/29 am Vienna International Airport.

The work will take place during a continuous day/night operation.

2

General renovation of the runway system 11/29 am Vienna International Airport.

Runway renovation works at Vienna International Airport

Do you have questions about the project or would you like to learn more? Feel free to contact us for further information.

**PORR AG Group Communications**

Absberggasse 47

1100 Wien

T +43 50 626-0

E-Mail: [comms@porr-group.com](mailto:comms@porr-group.com)