



High-pressure flushing and rehabilitation of sewers at Rosenheim Central Railway Station

Data and facts

Company

Type Liner, Inspection

Principal DB Munich

[Project report online](#)

www.porr-group.com



High pressure for a successful rehabilitation.

The contract also included the installation of a lifting system, the construction of the associated drainage channels on the station forecourt, and the rehabilitation of shaft structures.

Impressions




Image notes

1

Ready for action.

Last check of the special equipment for the upcoming sewer rehabilitation at Rosenheim Central Railway Station.

2

A look behind the scenes.

A familiar sight for the THORN specialists but exciting for outsiders: The interior view of a rehabilitation vehicle for inliners.

Do you have questions about the project or would you like to learn more? Feel free to contact us for further information.

PORR AG Group Communications

Absberggasse 47

1100 Wien

T +43 50 626-0

E-Mail: comms@porr-group.com