



# Rock instabilities K2 Gotthardstrasse

## Data and facts

Company	PORR Equipment Services Deutschland GmbH
---------	--

Type	Rock technology
------	-----------------

Runtime	10.2020 - 11.2020
---------	-------------------

Principal	Canton Uri, Office of Civil Engineering
-----------	---

[Project report online](#)

[www.porr-group.com](http://www.porr-group.com)





# Rock demolition hanging from the rope.

Most of the work was executed hanging from the rope. We not only removed the unstable rock, but also carried out urgently needed rock securing and anchoring work. In accordance with our motto "safety first", the entire operation on the rock was carried out under permanent securing and re-securing work.

## Impressions



## Image notes

1

**Safety first.**

Our rock team worked day and night perfectly secured hanging from the rope.

2

**Rockfall under controlled conditions.**

The rock was safely transported onto the closed cantonal road by our rock team.

Do you have questions about the project or would you like to learn more? Feel free to contact us for further information.

**PORR AG Group Communications**

Absberggasse 47

1100 Wien

T +43 50 626-0

E-Mail: [comms@porr-group.com](mailto:comms@porr-group.com)