

Overpass restoration and footbridge construction

Data and facts

Company	PORR SUISSE AG
Туре	Bridge construction
Runtime	11.2014 - 08.2015
Principal	SBB AG

Project report online



Work above high voltage.

Parts of these works took place directly above the 15,000-volt overhead wiring for the railways and lasted for a total of nine months, during which rail and road traffic could not be interrupted.

Impressions







Image notes

1 P

Pedestrian overpass in three sections.

The new steel pedestrian overpass spans almost five full platforms in three sections.

2

Exciting nine months.

Within just nine months, the entire project—restoration of the overpass as well as new construction of a footbridge—was complete.

Caution, high voltage.

The presence of the overhead wiring of the railway directly beneath a section of the works represented a particular challenge.

Do you have questions about the project or would you like to learn more? Feel free to contact us for further information.

PORR AG Group Communications

Absberggasse 47 1100 Wien

T +43 50 626-0

E-Mail: comms@porr-group.com