



Pipe lining of sewers, Spaten Brauerei in Munich, Germany

Data and facts

Company

Type Rehabilitation, Inspection

Principal Anheuser Busch Germany

[Project report online](#)

www.porr-group.com

PÖRR

Rehabilitation during brewing.

THORN mastered numerous challenges in the course of this project – apart from the technical implementation. Because the refurbishment was carried out during ongoing brewing operations, compliance with strict hygiene guidelines was a prerequisite. Additionally, the rehabilitation work was carried out in logistically sensitive areas such as loading yards and storage cellars. Thus it was partially only possible to carry out the work at the weekends.

Impressions



Image notes

1

Ready for inspection.

The equipment is unloaded: A THORN employee with the inspection vehicle directly before deployment in the Spaten Brauerei in Munich.

© PORR

2

Quick installation of a preliner.

THORN's specialists are also used to working under time pressure and in logistically sensitive areas, such as here at a crossroads in front of the Spaten Brauerei.

© PORR

Do you have questions about the project or would you like to learn more? Feel free to contact us for further information.

PORR AG

Absberggasse 47

1100 Vienna

Austria

+43 50 626-0

office@porr-group.com

#HomeOfConstruction