

Rehabilitation of sewers, Hotel Hilton Munich Park

Data and facts

Type Rehabilitation

Principal Hotel Hilton

Project report online

www.porr-group.com



Reconstruction for Hotel Hilton Munich Park.

Impressions







Image notes

1

Start of cosmetic work.

After the reconstruction of the shaft entrances, the THORN paving specialists started their work.

3

Camera investigation as a basis.

A camera inspection is often the first step in recording the damage. With the right equipment, THORN Abwassertechnik is armed for all needs and applications.

2

Automation in sewers.

This milling robot was used in the course of the "Hotel Hilton" project to mill the branches.

Do you have questions about the project or would you like to learn more? Feel free to contact us for further information.

PORR AG Group Communications

Absberggasse 47 1100 Wien

T +43 50 626-0

E-Mail: comms@porr-group.com